



Made In America

## **Large Display Air-Temperature Display**

3 Digit Range from – 99 °F to 150°F / Accuracy 1°F

2 Digit Range from – 99 °F to 99°F / Accuracy 1°F

### **Installation**

Mount Large Display unit in desired location. Connect AC Adaptor to 110V outlet.

Route The sensor Cable to the area that temperature is being monitored.

If Nylon Wire Ties Are used to secure the Sensor Cable DO NOT over tighten

### **Sensor Cable Replacement**

If the Sensor Cable Assembly is Damaged you may Purchase a new cable assembly from TIPTEMP for a Nominal charge.

The new cable assembly will have instructions on how to re-calibrate the gauge

### **\*\*Life Time Warranty\*\***

Excluding Sensor Cable Assembly & abuse

Customer must return unit back to TIPTEMP post paid