



Irreversible Temperature Labels

Instructions for Use

Peel indicator from release paper

Apply to any clean, grease free surface ensuring that the indicator has adhered to the surface

A color change from silver white/orange to black indicates that the temperature has been reached

Store in cool dry place below <64°F &< 50% relative humidity